

# Part-1

## Performa for the Safety School Building (To be filled by the Head of School/ Institute)

1. Name of School : SACRED HEART CONVENT SCHOOL
2. Location : SARABHA NAGAR, LUDHIANA
3. Plot Area : G.F. F.F. S.F. T.F. = Total
4. Plinth Area : 69870 - 44492 - 34885 - 14124 = 163
5. Number of Storey : 3 G + 4 (163)
6. Year of Construction of Building : 2005
7. Supervision of the qualified Engineer,  
The following details may be given :
  - a) Name of the Engineer : R. D. P. SHARMA
  - b) Address : 25, ATAM NAGAR, LDH.
  - c) Set of Structure Drawing used in the  
Construction if available : ATTACHED
  - d) Name of the Architect : VIKAS SHARMA
8. Whether the building has been constructed for the purpose of :
  - a) School (Yes/ No) : YES
  - b) Residential purpose and converted  
for use as a school (Yes/ No) : NO
9. Materials used for Roof :
  - a) R.C.C Slabs (Yes/ No) : YES
  - b) R.S. Joists and Battens (Yes/ No) : NO
  - c) Wooden Joists and Battens (Yes/ No) : NO
10. Materials used for walls :
  - a) Mud Mortar (Yes/ No) : NO
  - b) Cement Mortar (Yes/ No) : YES
  - c) Plaster (i) Lime Mortar (Yes/ No) : NO
  - (ii) Cement Mortar (Yes/ No) : YES
11. Flooring:
  - a) Conglomerate (Verified Tiles) (Yes/ No) : YES
  - b) Terrazzo (Yes/ No) : NO
  - c) Brick Paving (Yes/ No) : NO
12. Detailed Drawing indicating dimensions  
of the rooms along with size and location  
of doors and windows : ATTACHED

Signature with stamp of  
The Head of the School/ Institute  
Principal  
Sacred Heart Convent  
Senior Secondary School  
Sarabha Nagar, Ludhiana

2023-24/54

dt 3/5/2023

**PART-II**

(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 02/5/2023 and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto 31/3/2024  
(indicate upto which it can be used)

**ATTESTED**

*[Signature]*

Manager

Sacred Heart Convent School,  
Sarabha Nagar Ludhiana

**ATTESTED**

*[Signature]*

Principal

Sacred Heart Convent  
Senior Secondary School  
Sarabha Nagar, Ludhiana

*[Signature]*  
**Sub Divisional Engineer**

Sub Divisional Engineer,  
Provincial Sub Division No. 3,  
P.W.D. B&R, Br. LUDHIANA.

*m*  
02/5/2023